

August 2009

RI10012

II. Power and Control

- ___ 2 ETC Sensor racks (24 x 2.4K)
- ___ 1 ETC rack (36 [out of 48 work] x 2.4K)
- ___ 1 ETC Express 250
- ___ 1 100' DMX cable
- ___ 6 circuit A/B switch box
- ___ 14 6 Channel Multicables, lettered A-N (H5 is NFG)
- ___ 12 FOH Singletons

II. Lighting Instruments

Qty	Unit	Wattage
___ 24	6" Fresnel (500w BTL)	500
___ 10	6" Fresnels (750 w)	750
___ 4	8" Fresnel ((1000w BVV)	1000
___ 3	Source 4 19 degree (575w HPL)	575
___ 6	Source 4 26 degree (575w HPL)	575
___ 10	Source 4 36 degree (575w HPL)	575
___ 4	Source 4 50 degree (575w HPL)	575
___ 4	Altman 360Q – 4.5x6.5 (575w FLK)	575
___ 12	Altman 360Q – 6x9 (575w FLK)	575
___ 0	Altman 360Q – 6x12 (575w FLK)	575
___ 10	PAR64 WFL	1000
___ 10	PAR64 MFL	1000
___ 2	16 cell R40 Strip (3 circ) 8" long, lamped with flood	150/cell
___ 3	15 cell MR16 Strip (3 circ)	150/cell

III. Accessories Inventory

- ___ 4 Boom Bases
- ___ 6 Floor Mounts
- ___ 3 7.5 top hats
- ___ 6 7.5" barn doors
- ___ 4 Sidearms
- ___ 8 Extra C-Clamps, all units have own c-clamps

IV. Spare Box – Lighting

- ___ 1 575w HPL for Source 4
- ___ 1 575w FLK
- ___ 1 500w BTL
- ___ 1 Wide Lamp- PAR
- ___ 1 medium lamp - PAR
- ___ 1 narrow lamp- PAR
- ___ 1 75w –mini
- ___ 1 150w- R40

IV. Sound Equipment

- ___ 1 Mackie 1604 pro Mixing board
- ___ 1 Techniques CD Player
- ___ 4 Pulse speakers on the grid powered by Crown Ultra 1010 and Gem Sound PA500
- ___ 2 Radians PPX-108P Speakers in back of house powered by Crown XCS 202
- ___ 2 EV speakers setup as subwoofers under risers powered by UREI 6150
- ___ 2 Mackie C300 "specials" NO AMP AVAILABLE
- ___ 2 Corded Handheld Microphones
- ___ 7 XLR cables (5 @ 50', 2 @ 25')
- ___ 1 50' 9 channel snake

V. InterCom Equipment

- ___ 3 InterCom Headsets
- ___ 3 InterCom Headset Paks
- ___ 1 ClearCom AC Adapter Interface (w/Adapter)

VIII. LogBook

___ Every Show Safety/Fire Checked

VIV. Cable

Qty	Length
12	5 feet
10	10 feet
10	20 feet
7	25 feet
1	30 feet
2	50 feet
1	100 feet
12	2-fers
1	3-fers

X. Cable (under risers)

8	50 feet
3	100 feet

This is to verify that the company is provided with a full working inventory and spare box. The company agrees to leave a full and working and working inventory, including restocked Spare Box, upon strike.

Check-in:		
Production Representative: _____	Date: _____	Ohio Rep.: _____
Check-Out:		
Production Representative: _____	Date: _____	Ohio Rep.: _____

August 2009